



Schematic Diagram

01 PF




Joy Machinery (Shanghai) Co., Ltd Type: MAM6070 V.1


02 PM/MOTOR VSD




03 PF/VSD



04 FAN VSD



05 MOTOR/FAN VSD



06 SOFT START

